

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Screw "LLANASHE"

Rpt.

Sld.

No. 31972

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Longitudinal

Transverse No. 14620Depth "d" 24.75

Framing: Table No. _____

Description Bulb angle frames as approved2nd Longitudinal No. 37699

Proportions $\frac{\text{Length}}{\text{Depth}} = \underline{11.33}$

Deck Sheerstrake As approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1 "with freeboard," as recommended. The Summer freeboard of See from centre of disc Verification Form to top of statutory deck line at _____ deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

1 Dk. & Shelter Dk.

Cell. DB 361' 1207t, FPT 100t, APT 168t

BH

FK, 7 BH (Coll./to Shl. Dk. 6 BH to 2nd Dk.), Gem., Lloyd's A & CP.

© 2020

Lloyd's Register
Foundation

11.12.36