

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

23rd January 1922.

Dear Sir,

With reference to your First Entry Report No.1313 on the S.S."ECHUCA" I have to request that you will forward a Supplementary report on Form 1* stating the scantlings of the longitudinal frames and beams,transverses and transverse beams, etc.,as fitted in the ship.

I shall also be glad if you will state whether the thicknesses for $\frac{1}{2}$ length amidships of the shelter deck stringer and plating are .50 and .34 respectively,increased in way of the openings as approved; whether the riveting of the inner bottom plating is as required; whether the hawsers and warps are as required and not as stated; whether the numbers of rivets in the longitudinal brackets to the bulkheads are as approved; whether the chain cables are now in order and whether the indented plating on the starboard side has been repaired.

I am, Dear Sir,

Yours faithfully,

R.S.Taylor,Esq.,
BRISBANE.

© 2021

Secretary.

Lloyd's Register
Foundation

W1148 - 0028