

W1150-0104

0,29.

to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Sit S THE MONARCHReport Sls No. 50004**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey 1st Entry When due Revised Rules

✠ 100A.1. (Steel)

1 D^k (Stl). Well D^k

} Subject to examination in dry dock and permanent repairs to port bow plating at first convenient opportunity.

Cell D.B. 123' 174C, F.P.T. 56t, A.P.T. 22t.

F.K., 3 B.H., Cem, Ply do ACP.

Q 111', B 11', F 30'. machy apr.

(+ see Classing
minutes)



9.1.30
/

is concluded the thickness of the strake below the sheestake in the
ell is as approved but the Surveyor should be requested to state if this is no.