

3m,11,20.

- 7 MAY 1940

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME "TOGSTON" Rpt. Nwc. No. 98474

**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/32.*)

The Newcastle Surveyors report the vessel placed in dry dock, the bottom coated, the tank top plating under boiler repaired, the steering connections overhauled, and minor repairs effected.


Provision has now been made for the fitting of armament aft.

On account of damage through grounding and collision 12 shell plates and the framing in way have been repaired.

It is submitted the vessel appears worthy to remain as classed with record of survey 4.40.

100A1  
4.40 Shl.

The Certificate of Classification to be endorsed "*Cargo battens not fitted*" and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register  
Foundation

W1150-0254