

W1153-0143

1E

Received by Chief Engineer Surveyor _____ Received from Chief Engineer Surveyor _____

VESSEL'S NAME **OLIVIA** Rpt. **TRI.** **12604**
GMS. **20832**
AMS. **15659**
NWB. **96940**

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/33.

Type of Engine **Oil Engine 4 S.C.S.A.**
6 cyl. 25 9/16" - 55 1/4"

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner **Yes.**

If fitted with an outside gland of approved type **No.**

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **+ L.M.C. 7.39.**

D.B. 180 LB.

Surveyor should confirm length of stroke of main engine as the sister ship stroke is given as 1400 mm. also it is concluded that a 6 1/4" emergency bilge suction is fitted in engine room but this should be confirmed.

See letter 5/8 39. [Signature]

[Signature] 20/7/39



© 2020

Lloyd's Register Foundation