



# Lloyd's Register of Shipping.

4 Bridge Street, Sydney, N.S.W.

19th December 1941.

reference

The Secretary,

WOKINGHAM.

Dear Sir,

With reference to my report No. 18577 on the T.S.M.S. "OPAWA" forwarded to you to-day, it has been noticed that the wear down of the tail shafts was omitted.

These are Port  $1/16$ " and Starboard  $3/32$ ".

It is regretted that these were not entered on the Report.

I am, Dear Sir,

Yours faithfully,



© 2020

Lloyd's Register  
Foundation

W1153-0198

Notes  
TRM

24 FEB 1942

H  
R  
J

*[Faint signature]*



© 2020  
Lloyd's Register  
Foundation

Survey  
WB=C  
Total eq  
N.M.  
Last  
Periodic  
complete  
extent o  
should  
summa  
should  
respec  
In damag  
offere  
REPAIR  
Dk  
con  
in  
in  
in  
REPAIR  
SUMMARY  
Renov  
Rem  
Fair  
PRESENT  
Decks  
Caulking of  
Coamings  
Beams & T  
Outside Pla  
" "  
Breasthook  
Transoms  
Frames  
Reverse Ir  
Longitudin  
Transverse  
Floors  
Keelsons  
Stringers  
Inner Sot  
Gene