

Sm. 7.30.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Stl T.S. M/V "OPAWA"

Report

Els

No. 51471

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey

1st Entry

When due

Revised Rule

✠ 100 A. I. (Steel).

2 D^{rs} (Stl), 3rd D^r (Stl) in forward holds. "Rudder Electrically welded."

Cell D.B. 3H3' 1392t, tanks in way of tunnels 1005t, D.Ts/H' 294t, F.P.T. 88t, A.P.T. 94t.

F.K, duct keel forward of machinery space, 8 B.H, pt cem, Lloyds A C.P.

P 66' B 234' F 81'.



© 2020

Lloyd's Register
Foundation

Second Deck, amidships, Angle

Spacing

Through Plate or
Intercostal Plate...

8' x 3 1/2' x 3 1/2' x 4 1/2'

every frame