

of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Date of last survey and of Periodical Surveys.

+ 100A1

W1155-0027



Lloyd's Register of Shipping,

71, Fenchurch Street,

London, 22nd October, 1937.

E.C.3.

H.

To the Surveyors at GIBRALTAR.

See 9.11.37

4 NOV 1937

Vessel's Name, s.s. "SAN ZEFERINO".

d. QUESTION.	ANSWER.
<p>I shall be glad to receive a reply to the enquiry contained in my letter of the 10th ultimo.</p> <p><i>Ans.</i></p> <p><i>Record of that brought as per 1.10.37 and returned 20.9.37 by Capt. ...</i></p>	<p>Date:— October 27th, 1937.</p> <p>On the arrival of this vessel at Gibraltar, the new Owners stated that "they would hand me the load line certificate for return to London and cancellation". The certified copy was brought to my office but not the original. Subsequently the latter and the copy, the Owners have returned to London via The Anglo Saxon Pet: Co. Yesterday the Local Supt: informed me verbally that it was not intended to retain the vessels class.</p> <p><i>W.H.</i></p>

33-3
62-
law f
3.14
Carry
rd (if
p and
om?

ems :-

Copper, c
(Sta
When

Boats ...

Masts, Y

Condition

(State

Sails ...

Equipmen

Anchors,

Chain Lo

Cables (A

.. len

.. Ru

Hawser

Standing

el in the
remain as



© 2020

Lloyd's Register Foundation

Classed as
to Feb. 9. 11. 37

Submitted inquiry to
regarding the statement
not intended to retain that it is
class
6. 11. 37



© 2020
Lloyd's Register
Foundation

Journal of Shipping

21, Renshaw Street,

LONDON, E.C. 4.

ESTABLISHED

1827

Has a Survey also been made of the ...
If so, is the Report sent now, or when will it be sent?