

REEDPOOL

The [unclear] of the [unclear] may be [unclear]

**COPY.**

W1155-0071

November 1940.

The [unclear] reported No. 3 D.S. Tank examined on account of reported leakage and no leakage found, but the pumping arrangements were overhauled and cleared, afterwards tried and found satisfactory. No reference was made to heavy weather.

November 1940.

The [unclear] reported 18.11.40. account LLOYD'S REGISTER BELFAST  
[unclear] on voyage from 31st December 1940 to 4th January 1941, temporary repairs were effected in riveting in Nos. 4 & 5 D.S. tanks.

REEDPOOL TO COMPLETE BOILER SURVEY EXAMINE STARBOARD BOILER AND MOUNTINGS OF ALL THREE BOILERS EXCEPT MAIN CHECKS SCRUM AND BLOWDOWN VALVES ON PORT AND CENTRE BOILERS ADJUST ALL VALVES.

It is according COMMITTEE. The Owners be furnished as requested, with a statement of the [unclear] in the [unclear] Report No. [unclear]

Lloyd's Register  
Foundation

17.11.42.