

25th April 1942

W1155-0080

5-OCT 1942

ed by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SEL'S NAME "REEDPOOL" REPORT P.Sd. No. 2812

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

THE 2ND S.S. No.1, due 11.40, has been commenced by the examination of bottom, rudder and No.2 hold (after part used as bunker) also the testing and examination of No.2 D.B. tank (6.40).

Notation of 'Examined 9.41' valid for 12 months has been assigned.

The class is subject to indented shell plates A.2, 3 & 4, G.6, H.5, J.5 & 6 and K.5 (s.s.) being dealt with at the Owners' convenience and to the holds and peak tanks being re-coated at the first opportunity.

The PORT SAID Surveyor reports (4.42) the vessel afloat and repairs effected to the rudder.

It is submitted the vessel is worthy to remain as classed, subject as above.

As now, subject etc.

NOTE:- The validity of the Gen.Exam.has since expired.

© 2020

Lloyd's Register
S.S. PART HELD.

Foundation

length
(on board)
Rule length