

W1155-0084

Im. 8.21.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

S.S. "Reedpool"

Rpt.

Mdl.

No.

12099

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long.

Transverse No.

11212

Depth "d"

23.96

Framing: Table No.

213

Description

Channels, as approved.

Longitudinal No.

32779

Proportions

Length

13.56

Depth

Deck

Sheerstrake as approved.

Revised Rules.

This vessel received slight damage by collision and one shell plate has been renewed and one fixed in place.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100A1 (Stub)

1 Dk (Stl.)

all D.B. a 126' V.E. 25' f 171' 1059t. F.P.T. 162' A.P.T. 194t.
F.H. 6 B.H. New. Lloyd's A.V.C.P. P. 29' B. 221' F. 41'



2020
6.10.24
Lloyd's Register
Foundation