

Total

6903.36

Depth, at middle of length from top of keel to top of beam at side of innermost continuous

37.0

Owners Union Castle Mail

11-55, 2-40

Im, 9.37.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Single Sc.M.V. "ROWALLAN CASTLE" Rpt. Bel. No. 12335

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

1st Long. No. 16650 Depth "d" 9.0

2nd Long. No. 45000 Proportions = L/D 12.17

Framing Channel frames as approved Sheerstrake As approved

This is generally a sister ship to the "RICHMOND CASTLE"

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1

4 Dks.

Cell.DB 335' 1114t, Tanks at sides of tunnel 45' 326t, FPT 46t, APT 126t.

7 BH.

FK, Duct keel forward of Machy. space, pt.cem., Lloyd's A & CP.

B 121', F 48'

O.L. 474.2'.

*J. Jones*  
28.3.39



© 2019

Lloyd's Register Foundation

W116-0088

Spacing.....

thickness of Intercoastal Plate...