

COPY.

Lloyd's Register of Shipping.

Port NEW YORK

JUNE 2, 1942

This is to Certify that

W. BOYLAN

The undersigned Surveyor to this Society did at the request of the Owner's Representative survey the Steel Screw Steamer "AFSUN BETHRESS", 4034 tons gross of Middleborough, as she lay at New London, Conn., May 21st and 22nd, 1942 and subsequently on dry dock at Brewers Dry Dock Company, Mariners Harbor, Staten Island, N. Y. on May 26th and 27th, 1942 for the purpose of ascertaining the nature and extent of damage stated to have been sustained through collision with the Tug boat "E. Col. Matthews" while leaving anchorage off Little Gull, New London at 2:24 P.M. on May 20th, 1942.

For further particulars please see Vessel's log books.

On examination:

FIND

RECOMMENDED

Starboard side abreast of No. 1
hatch.

(1) bulwark plate badly
bent and bulb angle rail bent.
(1) bulwark plate slightly
bent.

To be removed, faired and re-
fitted.

To be faired in place.

(4) bulwark stays badly bent. To be renewed.

(2) bulwark stays slightly
bent. To be faired.

(1) 6" cast iron goose neck
pipe broken. To be renewed.

All necessary removals to effect repairs to be replaced in good
order.

All new and repair work to be recoated as before.

Necessary staging to effect repairs.

Surveyor to Lloyd's Register of Shipping

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly carried out, it is to be understood that neither the Society nor any Member of any of its Committees is under any obligation to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Committees, or for any error of judgment, default or omission in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or omission of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Printed in U.S.A.

W1164-0238

Lloyd's Register
Foundation