



NOTE:

1. PORTION OF CRACK NOT COVERED BY NEW PLATE TO BE CHIPPED OUT TO 60°V TO FULL DEPTH OF PLATE AND FILLED WITH WELD.
2. --- LINE INDICATES NEW PLATE.

REPAIR TO SHELL AT NO 5 TANK (STRD)

9/15/42
3- MR. COOK

MR. ATLANTIC SUN
BETHLEHEM STEEL COMPANY
(INCORPORATED)
SHIPBUILDING DIVISION
STATEN ISLAND YARD
SCALE 1/8"=1'-0" DATE 9/16/42
SKETCH NO. 17508-Y

W1166-0122

M/V "Atlantic Sun."

Repair to Shell
at No. 5. tank. (Stbd.)

Hyk. rept No. 42830.

W1166-0122



© 2021

Lloyd's Register
Foundation