


# CABLE AND WIRELESS LIMITED.

(5/-154)  
-154A



CABLE ROUTES  
WIRELESS ROUTES

Circuit.

VWZ  
A

Clerk's Name.

*[Handwritten signature]*

Time Received.

A.

1938 JUL 22 AM 9 20

701

3839 CALCUTTA 87 22 1305 =

COMMITTEE LONDON =

AYMERIC REFER CABLEGRAM FIFTH INSTANT STOP

VESSEL EXAMINED AFLOAT AND WITH EXCEPTION

SOME MODIFICATIONS AND FEW ADDITIONS REPAIRS

RECOMMENDED BY PESKETT CONCURRED IN AND WHEN



# Lloyd's Register of Shipping.

in England, Sept. 1937. (2,125 Pads).

5/-161

CONTINUATION SHEET No. 2

CABLE AND WIRELESS Ltd.

Name Com

Circuit Ref. 3839

COMPLETED VESSEL SHOULD BE IN EFFICIENT CONDITION

UNTIL NEXT SPECIAL SURVEY STOP ESTIMATED COST


OF HULL REPAIRS INCLUDING WORK ALREADY IN HAND

SEVENTY EIGHT THOUSAND NINE HUNDRED RUPEES

OP STERN TUBE MACHINERY REPAIRS DOCK DUES

ND OTHER INCIDENTALS TWENTY ONE THOUSAND ONE

W1166-0150 2/3



© 2021

Lloyd's Register  
Foundation



CONTINUATION SHEET No. 3

CABLE AND WIRELESS Ltd.

Name Com

Circuit Ref. 3839

HUNDRED RUPEES STOP TWISTED HULL BUCKLED DECKS

NOT APPARENT AFLOAT STOP UNLESS HEAR CONTRARY

WILL LEAVE MONDAY = BUTLER \*



© 2021

Lloyd's Register  
Foundation

W1166-015a 3/3



*Referred to the Chief Ship Surveyor,  
and the Chief Engineer Surveyor.*

*RS* *hnd*  
22 JUL 1938

*also for Mr. Sladden to note.*

*MR* *Sh*



© 2021

Lloyd's Register  
Foundation