

4 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

23 JUN 1938

NAME "AYMERIC"

Rpt. Yka.

No. 6420.

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

re endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/32.)

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Boiler Survey, due 3,38, partly held 3,38, completed.

It is submitted the vessel is eligible to remain as classed with record of survey BS 3,38 as recommended.

The class is subject to the circulating pump impeller casing being renewed at the first opportunity and the air pump casting being examined before the end of 6,38.

The Yokohama Surveyor reports an examination of the impeller casing and air pump casting. The latter was found in order.

A new impeller casing is on board and will be fitted at the first opportunity.

Screwshaft Survey, due 4,38-To be held at a Far Eastern Port-approved.


23.6.38.



© 2021

Lloyd's Register Foundation

w1166-0181

w1166-0182