



Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 1st September, 1937.

LLOYD'S REGISTER
2 - SEP 1937
LONDON

reference

S.

Dear Sir,

NO. 32183 "CORABELLA".

With reference to your letter of the 31st ultimo, we beg to state that the size of the cable feeding the 3 H.P. Refrigating Motor is 7/044 V.I.R. and not 7/029 V.I.R. as stated in the First Entry Report.

The entry of this circuit should therefore read:-

		Refrig. Motor	1	1	.01	7	.044
24	31	270	V.I.R.	In pipe.			

The figure of 28 entered for the total maximum current (Rule) in the chipping hammer circuit and in the wireless circuit should read 18.2.

We are, Dear Sir,

Yours faithfully,
THE SURVEYORS,
PER:

Gauterson

The Secretary,

LONDON.



© 2020

Lloyd's Register
Foundation

W1168-0084

ed to the Chief Engineer Surveyor

Handwritten initials

2- SEP 1857
Also for Mr. Hill to note.

noted in order.
hsd 2/9/37



© 2020

Lloyd's Register
Foundation

VESSEL'S
Received by

Im.1023

1st
2nd
Fram
Rules
be o