

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "CORABELLA" Rpt. Sld. No. 32343

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Sunderland Surveyors report this vessel placed in dry dock, bottom cleaned and coated.

The lower portion of the stern frame has been renewed on account of fractures etc.

Doubling plates have been fitted and connected by electric welding to the rudder plates where found fractured and part of the rudder plate on the starboard side has been renewed.

The width of the rudder has been reduced at the forward edge ^{FOUND TO BE CORRODED,} as per sketches in the report.

Zinc plates, which had not been previously fitted, have been installed.

It is submitted the vessel appears worthy to remain as classed with record of survey 4,38.

100A1
4,38 Sld.

[Handwritten signature]

CERTIFICATE WRITTEN
8.4.38

[Handwritten signature]

[Handwritten signature]
8.4.38



© 2020

Lloyd's Register
Foundation
WH68-0140