

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office \_\_\_\_\_

# Lloyd's Register of Shipping.

(Report on Vessel No. 32343 Port *Sunderland*)

No. *F7269* SHIP FORGINGS ~~OR~~ CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~ manufactured by *Wolsingham Steel Co. Ltd* of *Wolsingham* for the Vessel No. \_\_\_\_\_, being built by *S/S "Corabella"* of \_\_\_\_\_ have been inspected by me as set forth below and found to be, so far as can be seen, *Sound*

Forgings ~~or~~ Castings.

Lloyd's

No. *82*

D *30.3.38*

*J Dale*  
*Sunderland*  
*2. 4. 38*

*Keel piece*  
for STERN FRAME.

RUDDER FRAME.

STEM.

*1 m Ingot Steel*

*Forged*

*per*

*see sketch*

*Forging & Machining*

*30.3.38*

*Test No. 456*

CASTINGS.

on Standard Test Pieces.

Test—

per square inch

*22.0*

*39% ✓*

ending Test—

before fracture

*180° ✓*

Test—

cut from ground ...


ring Test—

made according to Rules

found satisfactory ...

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS. *74 cuts.*

The above Forging was Machined and finished by the Sunderland Forge and Engineering Co. Ltd.




Fee (if any chargeable) £ *2.15.6*

To be paid at *SUNDERLAND*

*2 APR. 1938*

of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

*W1168-0177*



© 2020

Lloyd's Register Foundation