

Rpt. 8.

(Received at London Office)

LA No. 8750

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report

19

When handed in at Local Office

19

Port of

Dar-es-salaam

No. in  
Reg. Book.

Survey held at

Date, First Survey

Last Survey

19

12541

on the ~~Wood, Iron or Steel~~ M.V. DONA AURORA.

(No. of Visits)

TONNAGE:

GROSS

5011

UNDER DK.

4467

NET

2977

Built at Trieste

By whom

Cantieri Riuniti Dell' Adriatico. When 1939 - 10.

Owners De La Rama S.S. Co. Inc.

Owners' Address

Manager E.H. Pirouano.

Port belonging to Gioia.

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell D Bor D Ba

feet; uE &amp; B

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

ast Report, No. 3181

Port C. Tch.

Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

AIRS, OR EXAMINATION AS PER RULE, FOR

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.D., if any).
+100AH with steelwork 4,42.	+LMC 10,39 TS.CL.3,42. Oil engine.

Camperly cargo oil F.P. etc. in tanks  
at sides of tunnel.Society's Freeboard (if assigned) as  
painted on Ship and now verified } ft. ins.

SUMMARY OF DAMAGE REPAIRS:—

Shell Plates.

Frames.

R. Frames.

Floors and  
Bracket Floors

Beams.

Inner Bottom  
Plates.

Dk. Plates.

Other Items:—

Renewed ...

Removed and Faired or Repaired

Faired or Repaired in place ...

PRESENT CONDITION OF THE

ing of Decks

ags

&amp; Fastenings

Plating

in way of sidelights

Frames

dinals

rises

s

s

ottom Plating

Tanks been examined internally?

Tanks been tested?

Bulkheads

Ceiling

Cement or Asphalt

Rudder

Steering gear and its connections

Windlass

Have pumps been examined and found effi-  
cient?Have Sluice Valves been examined and found  
efficient?Have Watertight Doors been examined and found  
efficient?Have Ventilators and their Coamings been  
examined and found efficient?

Air and Sounding Pipes

Doubling Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Openings, Covers, &amp;c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking

Caulking

Treenails

Breasthooks &amp; Stemson

Transoms, Pointers &amp; Crutches

Timbers of Frame at openings

" " at other places

Stringers, Clamps &amp; Shelves

Salting  
(State if examined.)

Copper, or Y.M.

(State if on Felt.)

When fitted, Month

Year

Boats

Masts, Yards, &amp;c.

Condition, how ascertained

(State if wedges removed.)

Equipment letter

Anchors, No. of

Cables (State if now ranged)

" length mean diamr.

" Rule length size

Chain Locker

Hawsers &amp; Warps

Standing and Running Rigging

Sails

al Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

(per Section 29)

£

:

:

Fees applied for,

19.

Damage or Repair Fee (if any)

£

:

:

Received by me,

19.

Travelling Expenses (if chargeable)

£

:

:

Second Surveyor's Fee (if any)

£

:


:

Committee's Minute

Character Assigned

THE 29 DEC 1942

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register  
Foundation

W1168-0267