

"EMPIRE FROST"

The Electrical Installation has been fitted on board under special survey, tested under full working conditions and found satisfactory.

The materials and workmanship are good.

All the requirements of the approved plans
and M. O. S. Specification have been carried out.

The Electrical Report is awaiting signature by
the Builders.

N. 4 Finala f

© 2020

30. 12. 40.

Lloyd's Register
Foundation

15/1/41.