

COPY

Lloyd's Register of Shipping,

14, Cross-shore street,
95, Bothwell Street, Glasgow, C.2.

GREENOCK.

2nd April, 1942.

Dear Sir,

M.O.W.T. INSULATED VESSELS.

Owing to the fitting of the suction trunk in the insulated holds of the above Vessels it is not practicable to fit the brackets to the double stiffeners at the hatch ends at Frames 101, 115 and 127.

The Builders state that they have been in communication with the Glasgow Office and it has been agreed to fit 6" x 6" lugs connecting the stiffeners to the tank top and also to fit a 6" x 6" foundation bar to the centre line bulkhead for two frame spaces in way of the hatch ends.

I shall be glad to have confirmation of this arrangement.

I am, Dear Sir,
Yours faithfully,

The Secretary,
GLASGOW.



© 2020

Lloyd's Register
Foundation

W1169-0110