

2500, 12, 19.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stl T.S. M/V EL ARGENTINO* Report *Sl* No. *47850*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey

First Entry

When due

Revised Rules

✠ 100 A.I. (Steel).

3 Dk (Stl - u.w.s.), 4th Dk (Stl) in holds.

Cell D.B. 369' 1672 t, tanks in way of tunnels 466 t, F.P.T. 78 t, A.P.T. 113 t.

F.K., Suct Keel forward of machy space, 8 B.H., pt Cen, Plyds A.C.P.

B 250', F 82'.



© 2020

Lloyd's Register Foundation

W1173-0212

PANTING ARRANGEMENTS (Sec. 7), state system and particulars

*Deep floors
over frames*

Thickness or remainder in floors Are Rule requirements complied with regarding increases of scantlings in way of double