

# REPORT ON BOILERS.

No. 427850

Date of writing Report 14 April 28 When handed in at Local Office 14 April 28 Port of Glasgow  
 No. in Survey held at Glasgow Date, First Survey 11.3.27 Last Survey 12.4.28  
 Reg. Book. on the T.S.M.V. "EL ARGENTINO" (Number of Visits 140) Tons { Gross 9501 Net 6023  
 Master — Built at Glasgow By whom built The Fairfield S.B. & Co. Ltd. When built 1918  
 Boilers made at 10444, 10445, 10446 When made 1918  
 Owners British & Argentine S.N.C. Port belonging to London

VERTICAL DONKEY BOILERS No. 3 Description Vertical Manufacturers of steel —  
 Made at Amman By whom made Cochran & Amman Ltd. When made 1918 Where fixed Engine Room Working pressure 125 lb.  
 Tested by hydraulic pressure to — Date of test — No. of Certificate 17734 Fire grate area 60 Description of safety valves Spring Loaded  
 No. of safety valves 2 Area of each 7.06 sq. ft. Pressure to which they are adjusted 125 lb. If fitted with easing gear yes If steam from main boilers can enter the donkey boiler yes  
 Dia. of donkey boiler — Length — Material of shell plates — Thickness — Range of tensile strength —  
 Descrip. of riveting long seams Dia. of rivet holes — Whether punched or drilled — Pitch of rivets —  
 Lap of plating — Per centage of strength of joint — Working pressure of shell by rules — Thickness of shell crown plates —  
 Radius of do. — No. of Stays to do. — Dia. of stays — Diameter of furnace Top 47 1/2 Bottom 47 1/2 Length of furnace —  
 Thickness of furnace plates — Description of joint — Working pressure of furnace by rules — Thickness of furnace crown plates —  
 Radius of do. — Stayed by — Diameter of uptake — Thickness of uptake plates —  
 Thickness of water tubes —

The foregoing is a correct description,

Manufacturer.

Dates { During progress of work in shops - - } See Accompanying  
 { During erection on board vessel - - } Machinery report  
 while building { Total No. of visits 140 }  
 Is the approved plan of boiler forwarded herewith yes

GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.)


These boilers have now been fitted on board the above vessel

Survey Fee ... £ — : : When applied for, ... 19...  
 Travelling Expenses (if any) £ — : : When received, ... 19...

W. Lane  
 Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute GLASGOW 24 APL 1928

Assigned See accompanying report.



© 2020

Lloyd's Register Foundation

W1173-0219