

M.S. "RICHMOND CASTLE"

The contents of the Owners' letter dated 17th instant are noted.

As the original repair was effected so long ago as December 1940 and as the Greenock Surveyor who carried out the Survey (Mr. R.M.Scott) is no longer in this country, it is not thought that any useful action can now be taken.

*Write to West Junction
for further comments
WJ*



© 2021

25th July, 1942.

Lloyd's Register
Foundation

W1175-0016