

be Shaft, diameter as per Rule
as fitted
Screw Shaft, diameter as per Rule
as fitted
Is the tube screw shaft fitted with a continuous
Is the after end of the
as per Rule
as fitted
Thickness between bushes
as fitted

(Received at London Office..... 1 FEB 1936.....)

9.1.36.

No. Place Date 1st January 1936

TEST BED
729/19/36

We request that the Committee of Lloyd's Register will instruct
Society's Surveyors to inspect one "CD" type, 7 h.p. and four
"CE" type, 14 h.p. Engines

We undertake to arrange for every facility to be given to the
Surveyors to carry out the duty in question, and we agree to pay the fees
for the Surveyors' services, in addition to the actual travelling and other
expenses incurred by the Surveyors in connexion therewith.


This request is made upon the terms of the Rules and Regulations
of Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

W.D. & H.O. WILLS LTD.
R. A. LISTER (MARINE SALES) LTD.

DURSLEY, Glos. © 2020

To the Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.



Main Air Compressors, No. No. of stages Diameters Stroke
Auxiliary Air Compressors, No. No. of stages Diameters Stroke