

URGENT

Arthon town

Rot. 24880

Before this case receives the Consideration of the  
Committee Submitted the Report on Electric Lifting  
be returned to the Rot. Surveyors. for completion of those  
items which have been omitted

Particulars of propeller should be stated

What means are provided for circulating water thru' the  
Cooler. & they should state whether the auxiliary compressor  
is hand starting

The Dusseldorf Surveyors should forward particulars  
of the air receivers as these do not appear to have been  
received

Yours

27.10.26



© 2020

Lloyd's Register  
W1176 0218  
Foundation  
How  
Are the  
or Cocks

Are all sea connections fitted direct on the skin of the ship  
Are they fixed sufficiently high on the ship's side to be seen without lifting the platform plates  
Are the Blow Off Cocks fitted with a spigot  
Are the Overboard Discharges above  
Are the Blow Off Cocks fitted with a spigot