

what parts of the Boilers could not be thus thoroughly examined?

what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

### MEMORANDUM

**From:** LLOYD'S REGISTER OF SHIPPING, HIGH CLOSE, WOKINGHAM. (Ref. H)

**To:** The Surveyor(s) at BRISTOL.

Date: 19th February, 1943.

**Vessel's Name:** S.S. "BRISTOL CITY."

**Question:** I shall be glad if you will ascertain and let me know what arrangements the Owners propose making to carry out the General Examination which will become due on this vessel at the end of the present month.

You will observe that the Screwshaft Survey became due at the end of January and that the Boiler Survey will become due at the end of next month. *RLB*

**Answer:**

Date: 1-3-43.

The Owner's Representative states that the General Examination & Boiler Survey will be carried out upon vessel's return to this country towards the end of the present month.

Lloyd's Register  
Foundation

It is recommended that the item is not to be used as now deleted  
Special Order & List