

COPY.

Lloyd's Register of Shipping.



Port MONTREAL, P.Q.

August 4th, 1941.

This is to Certify that

H. G. SAUNDERS

the undersigned Surveyor to this Society did at the request of

The Owners' representative attend at the Works of Canada Foundries
Three Rivers, Quebec, on 2nd August 1941, for the purpose of examining
and witnessing the tests of one main engine diesel cylinder liner stated
to be for the M/V "SALLY MAERSK".

A surface examination of the liner, which was fully machined, revealed
no surface defects, it being then subjected to a hydrostatic test of 100
lbs. per sq. in, and proven tight.

For identification purposes this liner has been marked as follows;-

LL O Y D S

No. 1910

H.G.S. 2/8/41

(Sgd.) H. G. SAUNDERS

SURVEYOR TO LLOYD'S REGISTER.

Fee; \$15.00

R.F.B. # 2499

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

NOW DONE;- Ford, auxiliary opened up, pistons and valve bearings etc., examined.

Crank shaft replaced with spare.

No. 6 cylinder liner and cylinder head replaced by spares on hand.

No. 1 Port and No. 6 Starboard column where fractured at foot, repaired by 3/4" steel bracket fitted both sides of flange with fitted bolts.

No. 3 auxiliary bed plate examined.

Ballast Pump Motor armature rewound.

Electric cables for windlass, winches and steering gear motors renewed throughout.

(Sgd.) I. J. TAIT

SURVEYOR TO LLOYD'S REGISTER.



© 2020

Lloyd's Register
Foundation

W113-0101(2/2)