

W1190-0116

Failures of this kind have been
specially noted & steps have been
taken to prevent recurrence of such trouble
when dealing with plans for later
vessels

Transverses.....✓	efficient? ✓	Transoms Pointers, & Crutches ditto.....	Cables (State if n
Floors.....✓	Have Watertight Doors now been examined and found	Timbers of Frame at openings ditto.....	" length.....
Keelsons.....✓	efficient? <i>not now examined</i>	Ditto Ditto at other places ditto.....	(on hog) " Rule length.....