

2m, 11, 26.

W. 178 Sect 2

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Stl Se " MATRA " Report Snk No. 18624**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey 1<sup>st</sup> Entry When due Revised Rules Rules


✠ 100 A. I. (Steel)

2 D<sup>ns</sup> (Stl), 3<sup>rd</sup> D<sup>n</sup> (Stl) in No 1 Hold

Cell D.B. 395' 1469t, D.T. 36' 1197t, F.P.T. 72t, A.P.T. 86t.

F.K, 8 B.H. (1 B.H. to 2<sup>nd</sup> D<sup>n</sup>), ft cm, Lloyd A. CP.

P 46', B 158', F 39'.

1764  
4-0-0

 © 2021  
 Lloyd's Register  
 Foundation  
 12.26  
 1192-0123

Flat Plate Keel Angles

Spacing..... EVERY