

Encl.

RECEIVED
13 JUL 1943
WOKINGHAM

Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,

Hull, 12th July, 1943.

Dear Sir,

In reply to your letter of the 9th inst., regarding the Steam Trawler "STRATHLYON" (our Report No. 51969), the damage referred to in the Reykjavik Report was examined by us and our recommendations are as follows:-

- 1 Sheerstrake plate breast trawl winch, p.s., indented -
renew at Owners' convenience.
- Bulwark plate adjacent to same, indented, fair in place.
- Gunwhale angle in way, crop and part renew.
- Stringer plate in way, buckled, fair in place.

The temporary repairs effected at Reykjavik are considered efficient for the time being and we recommend that permanent repairs be carried out at the Owners' convenience.

We are, Dear Sir,

Yours faithfully,

The Surveyors,

Per:-

John Douglas

The Secretary,
WOKINGHAM.

P.S. The Reykjavik Report is returned herewith.

W1183-0032

H

R. J. J.

13 JUL 1943

Yls



© 2020

Lloyd's Register
Foundation