

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report

When handed in at Local Office

Port of

Gibraltar

No. in Reg. Book. Survey held at

Date, First Survey

Last Survey

19

(No. of Visits)

34127 on the Machinery of the Wood, Iron or Steel

Steamer Stanhall

Tonnage { Gross 4831
Net 2810

Vessel built at

Hartlepool

By whom

W. Gray & Co. Ltd.

Year. Month.

When 1932 8

Nominal Horse Power

467

Engines made at

do.

By whom

do.

When

No. of Main Boilers

3

Boilers, when made (Main)

(Donkey)

No. of Donkey Boilers

3

Owners

Stanhope S. Co. Ltd.

Owners' Address

(if not already recorded in Appendix to Register Book.)

Steam Pressure—

260

Managers

J. A. Hillman & Co. Ltd.

Port

London

Voyage

in Main Boilers

If Surveyed Afloat or in Dry Dock

(State name of Dock.)

in Donkey Boilers

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
X for Special Survey
Date of last Survey and of
Periodical Surveys.Years
assigned
now
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).

+ 100 M

with lubrication

11.39

+ LMC 7.36

BS 11.39

CAN 9.39

St. Hpl No. 1-36

Last Report No. 2310 Port Ddn

Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Has screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, E.&M.S. 9, 11, & L.M.C. 9, 11, or L.M.C. 140 lb., F.D., &c.)

CS 5, 34,

Survey Fee (per Section 29) £ : :

Fees applied for

Special Damage or Repair Fee (if any) (per Section 29.) £ : :

Received by me,


Travelling expenses (if chargeable) £ : :

19

Committee's Minute

Assigned

No action



© 2020

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation

If a Certificate required? If so, to be sent to