

"Empire Birch"

Kel. 51472.

It is submitted the Surveyors be thanked
for confirming the particulars of the dynamo.
The attached dynamo test certificate should
however be returned to them as it does not
appear to refer to the "Empire Birch" may perhaps
the attached forging report F. 1587 may perhaps
refer to Cook, Mellen vessels in building. L.H.
20/2/42.

Clear in 20/2



© 2020

Lloyd's Register
Foundation

The Surveyors should be referred to Section 32 Clause 1(a) of the Rules
to state whether the omission of cement on the bottom