

COPY.

Lloyd's Register of Shipping.



Port

BOMBAY.

3rd APRIL 1944.

W1185-0050

~~RECEIVED~~ This is to Certify that I have

Surveyed the Steel Screw Steamer "EMPIRE HARRY" 479 tons gross

of Goole, as she lay afloat in Bombay Harbour for damage stated to have been caused (1) whilst manoeuvring close to A.P.D. 23 in order to put a harbour tow on board on the 1st March 1944 at 11.40 hours. (2) after slipping the harbour tow and closing with A.P.D. 23 in order to connect a sea tow on the 1st March 1944 at 17.20 hours. Both damages being whilst leaving Bombay and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report, stating that all repairs

recommended by me have been completed to my satisfaction, and

I have Recommended that she be continued in her present

class without fresh record, subject to bulwark plate etc. at after


and and to portside sheer plate etc. below bridge being dealt with

at Owner's convenience

being fit to carry

~~RECEIVED~~
John Rundell
Surveyor to Lloyd's Register.

Upon the terms of the Rules and Regulations of the Society, which provide that —
the Society use their best endeavours to ensure that the functions of the Society are
and that neither the Society nor any Member of any of its Committees is under any
for any inaccuracy in any report or certificate issued by the Society or its
or other publication of the Society, or for any error of judgment,
Member thereof, or the Surveyors, or other Officers or Agents of



© 2020
Lloyd's Register
Foundation