

(if assigned)

a.10.43.

25 JAN 1944

to Chief Surveyors.....

Received from Chief Surveyors.....

SSEL'S NAME "GRENA" REPORT Bal. No. 7924

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey DMG. & 2ND S.S. No.2 ~~When due~~ 12.42.

Subject to the rudder post of sternframe at E.W. 6.36, reinforced 1.37, rewelded 6.40, E.W. 10.41, rewelded 7.42, rewelded and reinforced 10.43 at the 19'- 6" to 20'- 6" draught marks and solepiece E.W. and reinforced 10.41 and 10.43 being specially examined at the next dry docking.

(B)

Wally
18.1.44



© 2020

Lloyd's Register Foundation

W1188-0166

To the Surveyors,

standing and Run