

3m. 9.20.

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Stl Se "DALFRAM" Report Gr No. 19185

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry When due Revised Rules

✠ 100 A.I. (Steel) "With Freeboard"

1st D^K (Stl) + Shelter D^K (Stl)

Cell D.B. 346' 1065 t, D.T.a 25' 904 t, A.P.T. 42 t

F.K, 6 B.H. (Coll B.H. to Shelter D^K, 5 B.H. to 2nd D^K) Cam, Lloyds ACP.



© 2020

Lloyd's Register
Foundation

W1189-0179

in Register Book.

Freeboard

3

ft.

4 1/2

ins.

0.00

ON EVERY