

Surveyors _____

Received from Chief Surveyors _____

NAME Steel S.S. "S I R I S".

Report

Grk.

No. 17541

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey _____

When due _____

The Downton Pump has been dispensed with for the present.

• 100 Al (Steel).

2 Dks. (Steel)

Cell DB 340' 1051t. FPT 128t. APT 220t.

FK 7 BH. P^tCem. Lloyd's A & C.P. P50'. B 113'. F 39'.

29.

M
18. 10. 19

for York 9/12/1919

me taken 10/12/19

It is concluded that the hatches are strong & efficient, but the Surveyors should be requested to state if this is so, and whether the record of "Cem" should be made in this case, or "Part Cement" as in standard ships.



© 2020

Lloyd's Register
Foundation

W119-0212