

Hatchways, ventilators & coaming, deck & general equipment

Im.342

ent to Chief Surveyors.....

Received from Chief Surveyors.....

8/6/42

ESSEL'S NAME "NORVIK" REPORT N.Yk. No. 42379

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey Docking When due

NOTED

8.6.42.

was



© 2020

Lloyd's Register

BU900-0034

Bottom Plating	and sound efficient	Stringers, Clamps & Shelves	Standing and Running
the Tanks been examined internally? ✓	Air and Sounding Pipes	Saling	Sails
the Tanks been tested? ✓	Doubling Plates under Sounding Pipes ✓	(State if examined.)	