

...was a damage report made by anyone else? If so, by whom?

...the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?


S.S. Benares

W1191 - 0246

It is submitted that
this vessel is eligible for
THE RECORD. + LMC. 9.20. FD

R.M.

20/9/20



© 2020

Lloyd's Register
Foundation

TO WRITE ACROSS THIS MARGIN.

...crew shaft now been drawn and examined? Is it fitted with continuous liner? or two liners?

...shaft now been changed? If so, state reasons

djust
djust
onke
onkey
Donke