

V.

2m,7.41

1

20 DEC 1944

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "JUAN CASIANO" REPORT N.Yk. No. 45700

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey DAMAGE ~~FRITCH~~

Subject to handrails and stanchions being dealt with and to permanent repairs to indented stem plating etc. at the Owners' convenience, to permanent repairs to indented shell plating in way of No.4 tank (s.s.) at the first opportunity, to starboard after boat davits being renewed by 6.44 and to (a bower anchor being supplied).

DRILL SHELL NEXT S.S.
Vessel since reported as having foundered.



© 2020 *Wah*

19.12.44
Lloyd's Register
Foundation

W1196-0106