

2m1.18.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. "MUNERIC". Rpt. Bel No. 8138

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

This vessel was recently classed 100 A.1. and the Certificate endorsed "Cargo battens not fitted in tween decks".

From a letter now received from the Belfast Surveyors it would appear that cargo battens are fitted in the tween decks.

It is submitted "Cargo battens not fitted in tween decks" be deleted from the Register Book.



© 2021 30. 6. 19.

Lloyd's Register
Foundation

W1199-0092

pro The Surveyors.

1169-0091