

Did the Surveyor examine the Safety Valves of the Main Boiler? _____ To what pressure were they afterwards adjusted under _____

Did the Surveyor examine the Safety Valves of Donkey Boiler? _____ To what pressure were they afterwards adjusted under _____

_____ and of the Donkey Boiler _____

"SAN ALVARO", "SAN DEMETRIO",
"SAN DELFINO" and "SAN EMILIANO"

Owners:- Eagle Oil & Shipping Co. Ltd.

Rule length
300 fathoms.

<u>"SAN DEMETRIO"</u>	Rule length on board,
<u>"SAN ALVARO"</u>	45 fathoms removed.
<u>"SAN DELFINO"</u>	45 fathoms removed.
<u>"SAN EMILIANO"</u>	45 fathoms removed.

The cases of these vessels to be kept specially under review by Mr. Ward for equipment (Tayco cable).

W120-0080



© 2019

Lloyd's Register
Foundation

Please keep attached.

Lloyd's Register