

been caused
June 1931

18 JUN 1931

of Ship Surveyor _____
Received from Chief Ship Surveyor _____
NAME Steel Sc.3 Mst. "ANNAGHER" Rpt. Lon. No. 96413

Notes of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.
The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.

The London Surveyors report damage sustained to stem and stem plating through collision.

Temporary repairs have been effected.

The Surveyors recommend that permanent repairs be carried out before the end of July.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As now/Subject to

W1202 - 0046



© 2019
Lloyd's Register
Foundation

Surveyor to Lloyd's Register.

classed with
stem dama