

8 APR 1932

s.s. "BREEZY".

London 97348a.

The Boiler Survey due 2,32.

In reply to enquiry the Owners now write that they no longer require to class this tug with this Society.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

[Signature]
7.4.32
[Signature]

board (if
ship and
whom?

Items:—

Copper
(84)
Wh
Boats
Masts,
Conditio
(Sta
Sails
Equipm
Anchor
Cables
" R
" R
Hawser
Standin

vessel in th
to remain



© 2019

Lloyd's Register
Foundation

Survey Fee (per Section 29)£

Special Damage or Repair Fee (if any).....£
(per Sec. 29)

Fees applied for,

19

Received by me.