

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

CHARACTER.
For Special Survey.
Date of last Survey and
Periodical Surveys.

+100A1



Lloyd's Register of Shipping,

71, Fenchurch Street,

London,

E.C.3.

29 APR 1932

H.

To the Surveyors at

GRIMSBY.

C.

Vessel's Name, S.T. "RELIANCE II"

QUESTION.

ANSWER.

I shall be glad if you will ascertain and let me know what arrangements the Owner proposes making to complete the 2nd Special Survey No. 3 and also his intentions in regard to the carrying out of the Boiler Survey which became due at the end of last month.


I may say that a Notice in regard to the Special Survey was sent to the Owner on the 9th September 1931 to which no reply appears to have been received.

Date:—

21st May, 1932.

We have interviewed the Owner regarding these outstanding surveys and this gentleman informs us that he has decided to withdraw the vessel from class and will be forwarding us a communication to this effect in the course of a few days.

Handwritten signature: A. L. P.



2m.1.31.



© 2020

Lloyd's Register Foundation

Other Items:—

Copper
(S)
Wh
Boats
Masts,
Condit
(Ste
Sails...
Equipm
Anchor
Cables
Hawse
Standi

vessel in th
"to remain