

10 FEB 1932

"No.17"

London 97190a

The screwshaft survey and the Modified Survey of the Oil Engines became due in 11,31.

The Society's Surveyor at Istanbul now states, in reply to enquiry, that the Owners have now informed him they do not desire to continue the vessel's class with this Society.

He adds he understands that this vessel was only contracted to be built to the Society's Rules.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book, and three dots (...) inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

9.2.32.

The Secretary,
Lloyd's Register,
London. E.C.3.



© 2020

Lloyd's Register
Foundation