

E 1

VESSEL'S NAME

S.S. Pinna

Report

nwc

No. 41437

Remarks of the CHIEF ENGINEER SURVEYOR for the consideration of the Classing Committee.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

SPECIAL SURVEY OF MACHINERY AND BOILERS FOR S.S. No.

This Survey, due , partly held at

in has now been completed, and the following repairs done (due to

It is submitted that the vessel is worthy to have the record

+ LMC 3.01 as recommended. with notation of "elec light,"
Fitted for burning liquid fuel.

C.M.

29.3.01

H.S.

29.3.01

© 2020

Lloyd's Register
Foundation

W1205-0183

across wide water spaces 142

Working pressures by rules 216 46

Girders to Chamber tops: Material steel 2 Dep

Number and pitch of Stays in each 3-9 3