

5E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME S.S. "SINGU"Rpt. Rangoon No. 692

As of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey DAMAGE & WEAR AND TEAR.

Temporary repairs have now been effected to the blow down and circulating chest of port boiler.

Submitted the vessel is eligible to remain as classed with
of Survey SUBJECT ~~as recommended~~.
to the blow down and circulating chest being renewed
on vessel's return to Rangoon. at end of present voyage

W1206-0108



© 2020

Lloyd's Register
Foundation