

Enclosure



Lloyd's Register of British & Foreign Shipping,

2, Hare Street,

Calcutta, 10th. February 1909.

LLOYDS REGISTER,
LONDON.

REC'D 27 FEB 1909
ANS'D

Reference

S.

Sir,


Adverting to your letter (S) dated the 29th. October and mine of the 24th. November 1908 in reply thereto, respecting the case of the Steamer "SINGU", I beg to state that, in view of the Owners' Agents in Rangoon having acquainted me with their intention to permanently repair the defect in her bottom plating at Bombay about the 12th. instant, I have thought it well to place before the Society's Surveyor at that port some particulars of the case. I beg to enclose herewith, for your information, a copy of my letter to him and, from a perusal of the same, you will observe that I am of opinion that the small portion of the bottom plating immediately below the oil pipe suction in each oil tank is not covered with cement and that at this particular spot corrosion is probably active and may require to be dealt with in the manner suggested.

I am, Sir,

Your obedient Servant,

The Secretary,

London.



J. W. Fish

Lloyd's Register
Foundation

W1206 - 0139

